

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

1531
North
> 1
1.917 mi.
10120 ft.

VAULT 3760
AVE P/E OF WEST 10 ST
BROOKLYN, NY

NY Spills S106867829
N/A

Relative:
Higher

Actual:
20 ft.

SPILLS:

Name: VAULT 3760
Address: AVE P/E OF WEST 10 ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0500232 / 2005-12-23
Facility ID: 0500232
Facility Type: ER
DER Facility ID: 289605
Site ID: 343140
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2005-04-05
Investigator: SKARAKHA
Referred To: Not reported
Reported to Dept: 2005-04-05
CID: 73
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2005-04-06
Spill Record Last Update: 2005-12-23
Spiller Name: Not reported
Spiller Company: Not reported
Spiller Address: 40 ELDRIDGE AV
Spiller Company: 001
Contact Name: ERT DESK
DEC Memo: "e2mis no 157954 4/5/05 - 2158hrs - Ken Davis # 16852 - Mech A, BQE, reports while on location to inspect VS3760 when he opened the nwp door saw a secondary bushing leak and 2 oz transformer oil spilled onto concrete floor of structure. He closed door and contained leak. No sewers or waterways affected. Substance owned by Con Ed. The oil level in unit is 25 - and upon arrival found the unit at 3psi. Pressure test not recommended. Env. stop tag # 08294 placed. Sample being taken from unit. Clean up pending sample results and deenergization of fdr and also transformer removal. April 06, 2005 2:45 AM Lab Sequence Number: 05-03116-001 Aroclor 1260 < 1.0 ppm UPDATE 4/6/05 08:02 HRS ENV OPS GLODOWSKI REPORTS THAT COAGULANT WAS APPLIED TO THE SPILL, ALL WASTE REMOVED WITH VACTOR, THE STRUCTURE WAS DOUBLE WASHED WITH BIO-GEN 760, A SEALED SUMP WAS FOUND, AND THE ENV TAG WAS LEFT IN PLACE PENDING REMOVAL OF UNIT. Update - 8/31/05 - 1320hrs P. Rosado env. ops mech reports double washed structure with 760 biogen. Found cement sump in structure. Networks on location and has removed old transformer. New installation scheduled for today. Removed env. stop tag # 083294. Clean up completed 100 ."
Remarks: "2 OUNCES OIL SPILLED ONTO CONCRETE FLOOR. NO TO ALL 5 QUESTIONS. CON ED REF # 157954."

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

All Materials:

Site ID:	343140
Operable Unit ID:	1101820
Operable Unit:	01
Material ID:	582056
Material Code:	0020A
Material Name:	transformer oil
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported